

## ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 12/6/01	3. CCR #: 01-0913	4. Rev: —	5. Tel: 301 925-0703	6. Rm #: 2072C	7. Dept.
8. CCR Title: Removal of HPs from EDF						
9. Originator Signature/Date Maryellen Corbett /s/ 12/05/2001			10. Class IN	11. Type: CCR	12. Need Date: Dec. 15, 2001	
13. Office Manager Signature/Date Carolyn Whitaker /s/ 12/05/2001			14. Category of Change: EDF (RTSC)		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted: None			17. Schedule Impact:		18. CI(s) Affected:	
19. Release Affected by this Change: N/A		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) Migration of HPs to Sun was concluded at the DAACs 07/2001. A CCR removed all HPs at the DAACs (except for e0msh03 which will be retained only until DCE is removed. To provide needed power and space, the EDF HPs should be removed. The only HPs that should be retained are those currently used by Toolkit: relbhpm and beni. Knine will be retained for EMOS use and Mohawk; f2msh01 retained until DCE removal.						
24. Proposed Solution: (use additional sheets if necessary) Remove all EDF HPs, except relbhpm, beni, knine, f2msh01 and mohawk. The attached sheet identifies the machines and any detail that needs to be addressed before removal. ECOs for removal are also provided. M&O has reported that additional work needs to be done to remove files before the HPs are removed. somsh01, somsh02 and somsh03 will be removed later via another CCR.						
25. Alternate Solution: (use additional sheets if necessary) Retain machines that are of no practical use.						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Space and power will be used for unneeded machines.						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input checked="" type="checkbox"/> EDF <input type="checkbox"/> PVC <input type="checkbox"/> VATC <input type="checkbox"/> EDC <input type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date): Kevin Lange /s/ 12/12/01			Disposition: <b>Approved</b> App/Com. Disapproved Withdraw Fwd/ESDIS ERB			
33. M&O CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS Fwd/ESDIS			

## ADDITIONAL SHEET

**CCR #:**                      **Rev:**      **Originator:** Maryellen Corbett

**Telephone:** 0703      **Office:** 2072C

**Title of Change:** Removal of HPs from EDF

The following EDF HPs are to be removed and turned over to the ILS group for return to the Government.  
The ILS group will deinstall all software on these machines before returning it to the Government.

baltic  
eagle  
et3ws3  
mandela  
mulder  
navajo  
oriole  
otis  
pawnee  
prism  
relbhp  
relbhpcs  
slimer  
sparrow